



WHERE NEW LINK SEALS CANNOT BE INSTALLED IN EXISTING OPENING PROVIDE A GROUP OF EPDM RUBBER GASKETS EQUIVALENT TO LINK SEAL IN THICKNESS.



New York City Housing Authority
 Capital Projects Division
 Design Department
 90 Church Street, 10th Floor
 New York, NY 10007

Title:

***NEW CONDUIT
 IN EXISTING SLEEVE
 IN FOUNDATION WALL***

Contract Name:

GROUNDS REQUIREMENT

Contract No.

GD XXXXXXX

Drawn by:
 G. SOUKAS

Checked by:
 K. MARSHAL

Scale:

Not to Scale

Date:

January 2017

Drawing No.

ELE- 07